




Framework Plan

Cathedral Basilica | St. Augustine, FL
ML+H Project No. 17.22.0 | 08.07.17



0 10' 20' 40'



Oaks along one side of St. George Street



Existing "BoA" parking lot



Cast iron and coquina

Parking attendant and cones directing traffic



Poorly lit parking lot



Treasury Street traffic affecting landscape



Lack of buffer space



Colonnade blocks views



Vegetation taking over gathering space



Vegetation and shed detract from space



Existing courtyard space



Hidden statuary



Residential courtyard feels like landscape leftovers



Enlarged Parking Island

Enlarged Parking Island Surrounding Parking Lot Attendant Kiosk

New Parking Sign (See Detail)

Oak Trees to Complete Existing Canopy

Opening in Existing Wall On Center with Cathedral Gate (See Detail)


Remove Planter to Open Up Direction of Travel (Coordinate with COSA)

Two Parking Spaces Removed For Entry Way


Shift Parking Space

Trolley Tours Kiosk

Kiosk Waiting Area




Parking Sign



Renovated Wall along St. George Street







Elevation

Coquina Block Wall and Fountain Detail

Cathedral Basilica | St. Augustine, FL
ML+H Project No. 17.22.1 | 11.17.17





**Low Aluminum Garden Fence
On Coquina Foundation**

**Rectory Garden
Entry**

**Proposed Parish
Garden Entry**

Revitalized Shrub Plantings

Treasury Street